

## Soil Investigation, Level 3, DHR Standards

<b>Project Name:</b>	Highway 29 10-Acre Tract	<b>Project Number:</b>	068730.00
<b>Project Location:</b>	Royston, Georgia	<b>Investigation Date:</b>	February 8, 2006
<b>County:</b>	Franklin	<b>Performed By:</b>	Erin M. Harris
<b>Client:</b>	Building Wrights and Renovators 229 East Spring Street Crawford, Georgia 30630 Attention: Seavy O'Neal	<b>Client Phone No.:</b>	706.380.8001

Boring	Soil Series	Slope % Range of Soil Types	Depth to Refusal Layer (inches)	Depth to Seasonal High H <sub>2</sub> O Table (inches)	Absorption Rate At Recommended Trench Depth (min./inch)	Recommended Trench Depth (inches)	Suitability Code
B1	Gwinnett	5-15	48*	>48	See Codes	See Codes	I
B2	Cecil	5-15	>72	>72	60	48	A
B3	Cecil	5-15	>72	>72	60	48	A
B4	Gwinnett	5-15	36*	>36	See Codes	See Codes	I
B5	Cecil	5-15	>72	>72	60	48	A

\*Refusal layer (rock fragment) was encountered.

